



NOTE:
 A. ALL BACKFLOW PREVENTION ASSEMBLIES SHALL BE DELIVERED FOR INSTALLATION COMPLETELY ASSEMBLED BY THE ORIGINAL MANUFACTURER WITH ALL COMPONENTS AS APPROVED.
 B. CLASS 53 DUCTILE IRON TO VALVE. ALL JOINTS RESTRAINED.



DOUBLE DETECTOR CHECK VALVE ASSEMBLY DETAIL

REVISIONS:	DATE
	APPROVED: 06/03/2020
	PAGE No. 800-16